	W	ork	Order	ID	60020
--	---	-----	-------	----	-------

Packaging

Packaging



Page 1

Tuesday, June 22, 2010 3:24:21 PM Item ID: D4043-5 Accept Setup Start **Revision ID:** Stop Rib **Item Name:** Start Date: 6/22/2010 Start Qty: 2.00 **Cust Item ID:** Required Date: 7/30/2010 Req'd Qty: 2.00 **Customer:** Reference: Start Run Date: 10-62 Tooling: Process Plan: Approvals: Date: Stop QC: Date:_____ SPC (Y/N): Date: Sequence ID/ Operation Set Up/ **Tool ID** Tool # Plan Reject Accept Reject Insp. Work Center ID Description **Run Hours** Qty Qty Code Number Stamp Draw Nbr **Revision Nbr** D4043 Α 100 0.00 Large Fab 0.00 Memo AD 10-06-24 Large Fab 1- Cut as per dwg D4043 2- deburr and remove identification markings QC5- Inspect part completeness to step on W/O 110 0.00 Swalzy Memo Quality Control Identify as per dwg & Stock Location: 120 @ D 10.06.24

0.00

Memo

	-							
W/O:			V	ORK ORDER CHANG	ES			•
DATE	STEP	PROC	EDURE CH	IANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•						·
Part No	<u> </u> :	PAR #:	Fault Ca	tegory:	NCR: Yes	No. DQA:	Date: _	1
		esolution:						
NCR:		W	ORK OR	DER NON-CONFORMA	ANCE (NCR)		
DATE	STEP	Description of NC			ion B	Verification	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
							į.	
				·				
				. , .				
	Ÿ			·				
· -								

Work Order ID 60020

Tuesday, June 22, 2010 3:24:21 PM



Page 2

Item ID:

D4043-5

Accept



Setup Start



Revision ID:

Item Name:

Rib

Start Date: 6/22/2010 Required Date: 7/30/2010

Start Qty: 2.00

Operation

Description

Req'd Qty: 2.00



Cust Item ID: Customer:

Reference:

An	prova	ls:
ΔD	DIVVA	113.

Process Plan:

Date:

Tooling:

Date:

Run Start



QC: Date:

QC21- Final Inspection - Work Order Release

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop

Stop



Sequence ID/

Work Center ID

130

Memo

0.00

0.00

Tool ID

Tool # Plan Code

Accept Qty

Reject Reject Number Qty

Insp. Stamp

10/06/ CZ10/6/24

Quality Control

W/O:			WO	RK ORDER CHANG	ES				٢
DATE	STEP	PRO	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	jory:	NCR: Yes	No DQ	A:	Date: _	
		esolution:							
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	₹)			
DATE	OTED	Description of NC		Corrective Action Secti		Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date	Section Section	tion C	Chief Eng	QC Inspector
·									
	1		1 1			1		1	1

Picklist Print

Tuesday, June 22, 2010 3:24:25 PM

Work Order ID: 60020

Parent Item:

D4043-5

Parent Item Name: Rib



Start Date: 6/22/2010

Required Date: 7/30/2010

Page 1

Start Qty: 2.00

Required Qty: 2.00

Comments:


IPP RevA: new issue DD 10/01/05 verified by:EC revA DD 10.02.18 verified by:EC

IPP Rev:B as per dwg


Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304TS0.500W.049		Purchased	No		100	f	155.2554	1.99	4.189474			
Square Tubing									S	1-10	10-6	06-20

Location	Loc Qty	Loc Code	
MAT	148.1591158		
114004	. 0		
114426	9.2647		
114807	138.894416		4.1894
MAT018	4.4738		•
114004	0.5		
114161	3.9738		
WA	2.62251		
114724	2.62251		


W/O:			WO	RK ORDER CHANGE	S				ŕ
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	\ :	Date:	<u> </u>
		esolution:							
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR	1)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approvai	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector
-									
						ļ			



	-									
W/O:			W	ORK ORDER CHANGE	ES					ŧ
DATE	STEP	PRO	OCEDURE CHA	ANGE	-	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			*							
					!					
Part No	:	PAR #:	Fault Cat	egory:	NCR:	Yes N	lo DQ	A :	_ Date: _	_
	R	esolution:	Dispositi	on:	_ QA: I	VC Clo	sed:		Date: _	
NCR:			WORK ORE	ER NON-CONFORMA	NCE	(NCR))			
DATE	STEP	Description of NC		Corrective Action Section			Verific	ation	Approval	Approval
DAIE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector
					-					
**-										
:										
				,						



W/O:	-	•	V	VORK ORE	DER CHANGE	ES			***		ŧ .
DATE	STEP	PROC	EDURE CH	IANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
· · · · · · · · · · · · · · · · · · ·											
	-										
Part No	•	PAR #:	_ Fault Ca	tegory:		NCR	: Yes	No DQ	A:	_ Date: _	
	R	esolution:	_ Disposit	ion:		QA:	N/C CI	osed:		Date: _	
NCR:		W	ORK OR	DER NON-	-CONFORMA	NCE	(NCR)			
DATE	STEP	Description of NC	Initial	Corrective	Action Section Description	on B	Sign &		ation	Approval	Approval
		Section A	Chief Eng	ACIIC	Chief Eng		Date	Secti	on C	Chief Eng	QC Inspector
	· .										·
·				-			•				
									-	-	
			·								
						•					
	:										
										. •	



W/O:			W	ORK ORDER CHANG	ES				£ '
DATE	STEP	PRC	CEDURE CHA	NGE	Ву	Dat	e Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								1	
					·				
									
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: Yes	s No	DQA:	_ Date: _	
	R	esolution:	Disposition	on:	_ QA: N/C	Closed:	:	Date: _	
NCR:		\	WORK ORD	ER NON-CONFORMA	ANCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section			erification	Approval	Approval
DAIL	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Dat		Section C	Chief Eng	QC Inspector
				•			ļ		
İ									
·									
	1		1 1		Į.	1			1

- Ø0.297 - Ø0.191

wb 60020

D4043-9 BUSHING

NOTES:
1) MATERIAL: AISI 303 STAINLESS STEEL ROUND BAR
REF DART SPEC. M303R
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
7) WEIGHT: 0.006 lbs

DESIGN	RF	DART AEROSPA	CE LTD
DRAWN	RF	HAWKESBURY, ONTARIO	
CHECKED	W	DRAWING NO.	REV. A
MFG. APPR.	77	D4043	SHEET 4 OF 4
APPROVED	140	TITLE	SCALE
DE APPR.	-#	RIB ASSEMBLY	NTS
DATE 10.0	1.29	COPYRIGHT © 2010 BY DART AE THIS DOCUMENT IS PRIVATE AND CONSTIDENTIAL AND IS SUPPLIED OF NOT TO BE USED FOR ANY PURPOSE OR COMED OR COMMUNICATION.	H THE EXPRESS CONDITION THAT IT IS

8

D

С

Α

3

7

2

Dart Aerospace	Ltd
----------------	------------

W/O:			WO	RK ORDER CHANGE	ES				
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								Frou lings	
Part No	•	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	Date:	
		solution: Disposition:							
NCR:		,	WORK ORDE	R NON-CONFORMA	NCE (NCI	₹)			
DATE	STEP	Description of NC Section A	Corrective Action Section			Verification		Approval	Approval
			Initial	Action Description	Sign	Σ Coot		Chief Eng	QC Inspector
	ļ		Chief Eng	Chief Eng	Date		ion C	Chief Eng	
			Chief Eng	Chief Eng			ion C	Chief Eng	
			Chief Eng	Chief Eng			ion C	Chief Eng	
			Chief Eng	Chief Eng			t v	Chief Eng	
			Chief Eng	Chief Eng			t	Chief Eng	
			Chief Eng	Chief Eng			t	Chief Eng	
			Chief Eng	Chief Eng			t	Chief Eng	
			Chief Eng	Chief Eng			t	Chief Eng	
			Chief Eng	Chief Eng			t	Chief Eng	